



*BEFORE*

*Device works well, can be controlled from PC*



*NOW*



- Device does not work
- Device application software OK
- Virtual serial port pair OK
- Netwrk switch ok
- HF5122 OK. IoT Service software recognise it
- Cannot map serial port to TCP-IP

*Please assist to set up HF5122 to map virtual serial port to TCP-IP*